CLEANING LABORATORY EVALUATION SUMMARY

SCL #:	2016
DateRun:	07/18/2016
Experimenters:	James Keats
ClientType:	Cleaning Equipment Mfr
ProjectNumber:	Project #1
Substrates:	Vinyl Composite Tiles
PartType:	Coupon
Contaminants:	Food
Cleaning Methods:	Mechanical Agitation
Analytical Methods:	Visual
Purpose:	Evaluate beginning, middle, and end effectiveness of iRobot cleaning pad.

Experimental Procedure:

Apply soil to 4' X 4' clean vinyl floor, spreading 1g of soil onto even numbered tiles with a swab and odd tiles by dripping 1g of soil onto them (16g per floor). Allow the floor to dry for 48h. The tester then cleans the floor using paper towels and a spray bottle filled with water, beginning by the 1st tile. Tester continues to clean until they feel they have finished. The time it takes for the tester to clean the floor is recorded.

To evaluate total soil removal, a visual observation will be made. This observation will be an estimation of the % soil removed from each tile by comparing before and after pictures of the floor. In addition to this rating, observers will also be asked to rate the overall cleanliness of the floor from 1-5 (1 being no soil remaining).

Tile numbers

4	5	6	7
3	14	15	8
2	13	16	9
1	12	11	10

^^^

Tester starts here

Results:

The floor was soiled and cleaned once. The remaining soil on tile 7 was in the small divots of the floor.

Percent removal Trial 1

Time: 1 minute 40 seconds

(Ex: 95% means that 5% of the initial soil remained on the tile.)

Observer 1 – rating: 1.5

100%	100%	100%	95%
100%	100%	100%	100%
100%	100%	100%	100%
100%	100%	100%	100%

Observer 2 – rating: 1.5

100%	100%	100%	95%
100%	100%	100%	100%
100%	100%	100%	100%
100%	100%	100%	100%

.

Observer 3 – rating: 1

100%	100%	100%	95%
100%	100%	100%	100%
100%	100%	100%	100%
100%	100%	100%	100%

Summary:

	Vinyl Composite Tiles

CLEANING LABORATORY EVALUATION SUMMARY

Substrates:					
Contaminants:	Food				
Company Name:	**Product Name:**	**Conc.:**	**Efficiency:**	**Effective:**	**Observations:**
Water	Water	100	0.00	☑	

Conclusion: While the manually cleaned floor was rated as more clean than the floor cleaned by the Braava unit, it was still not completely clean.